

U. S. Department of Agriculture  
FOREST SERVICE

*Copied & Posted  
R-3 5/36*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 30 S. 5 Mer.

1/4 Corner common to Sections 19, 30, and


Corner consists of a iron stake- 150 ft. (not) in place east of fence in open field  
state condition

Dimensions above ground \_\_\_\_\_ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

(Signature)

(Date)

(Title)

Section 30

1910

Teacher

CORNER OF SECTION 30

2.175 ft N of stake

B 1 for 50-10 foot oak stub faced east  
19-10 oak-west of fence 25 ft

Corner

Give any further facts which will aid in finding this


chains distant

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer. R-3

R.

T.