

U. S. Department of Agriculture  
FOREST SERVICE

172  
7-22-21  
063  
A

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142 N* R. *30 W* *5th* Mer.

*1/4* Corner common to Sections

Corner consists of a *1" I.P. w/ cap* (not) in place


State condition *Good*

Dimensions above ground *4* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*1/2/27* (Date) *R. Moore* (Title) *F 48*

U. S. DEPARTMENT OF AGRICULTURE

FEDERAL BUREAU OF SURVEY

COAST AND GEODETIC SURVEY

STANDARD FORM NO. 1

Corner again.

Give any further facts which will aid in finding this

chain distant.

0.42

from which this corner bears


S 1/2 W

side of

tree 14 inches diameter, on the

*Survey line*

Metal Location Poster is on a



(Make sketch of topography near corner)

T. H. 2 N B 30 W  
5 H T-9  
Mer.