

U. S. Department of Agriculture

FOREST SERVICE

172
4-28-37
M9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N. R. 30 W. 5th Mer.

S 1/16

Corner common to Sections

16, and 17

Corner consists of a 1" Iron nail cap (not) in place



State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steinfeld

Aug 27, 1936 (Date)

Forest Soc. (Title)

U. S. Department of Agriculture

FOREST SERVICE

NATIONAL FOREST

CORNER OF THE PUBLIC SURVEY

Corner again.

Give any further facts which will aid in finding this

chain distant.

from which this Corner bears


SE 1/4

side of

tree inches diameter, on the

Metal Location Poster is on a

SE 1/4



(Make sketch of topography near Corner)

M. 9

B

(Cont)

T