

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

173  
1-28-21  
P. J. [Signature]

*Chippewa* NATIONAL FOREST N10

CORNERS OF THE PUBLIC SURVEY

T. *142 N* R. *30 W* *5<sup>th</sup>* Mer.  
*W 1/4* Corner common to Sections

*16*, and *21*

Corner consists of *1/2" M. W. brass cap* (not) in place



State condition *Good*

Dimensions above ground *7* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Carl Steadland*  
(Signature)

*Aug 26, 1936*  
(Date)

*Const. Fore*  
(Title)

W-10

UNITED STATES DEPARTMENT OF THE ARMY  
ENGINEERING CENTER  
FORT BELLEVILLE, ILLINOIS

PROJECT LOCATION

NAME OF THE OFFICER IN CHARGE

DATE OF REPORT

Corner again.

Give any further facts which will aid in finding this


chain's distant.

from which this corner bears *N 32° W*

side of

tree inches diameter, on the

*Corner*  
Metal Location Poster is on a



(Make sketch of topography near corner)

T. R. M.