

U. S. Department of Agriculture
FOREST SERVICE

P-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N. R. 30 W. 5th Mer.

C 1/4

Corner common to Sections

21, _____, and _____

Corner consists of a 1" I.P.W./brass-cap (not) in place


State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadman

(Signature)

Sept. 3, 1936.
(Date)

Const. For
(Title)

Faint, illegible text at the top of the page, possibly bleed-through from the reverse side.

Corner again.

Give any further facts which will aid in finding this


chains distant. *0.10*

from which this Corner bears *North*

side of

tree *1 1/2* inches diameter, on the

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

T. 142N R. 30N
5th Mer.
P. 11