

U. S. Department of Agriculture
FOREST SERVICE

179
1-22
1936

Chippewa NATIONAL FOREST *DP* *M13*

CORNERS OF THE PUBLIC SURVEY

T. *147 N.* R. *30 W.* *5th* Mer.

S¹/₁₆ Corner common to Sections
15, and *16*



Corner consists of a *1" I.M. w/ brass cap* (now) in place
State condition *Good*

Dimensions above ground *14* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*


If not, why? _____

Carl Steadland
(Signature)

Const. For.
(Title)

Aug. 25, 1936
(Date)

Metal Location Poster is on a *5* inches diameter, on the side of tree *NSAE* from which this Corner bears *0.74* chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)