

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Copied & Posted 5/36
L 13

----- NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 30 Mer. 5
1/4

----- Corner common to Sections
15, 16, -----, and -----

Corner consists of a iron stake (not) in place
 State condition -----

Dimensions above ground ----- inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

(Signature)

(Date)

(Title)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT


REPORT OF SURVEY

SECTION 16 - 6" ON 30 FT W.

Corner again.

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ obtain distant.

Give any further facts which will aid in finding this



(Make sketch of topography near Corner)