

U. S. Department of Agriculture
FOREST SERVICE

P, G-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142 N.* R. *30 W.* *5th* Mer.

1/64 Corner common to Sections
20, Located 9.55 chas. S. of C 1/4 S. 20

Corner consists of a *1" I.P.W. cap* (not) in place



State condition *Good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

2/7/37
(Date)

R. Moore
(Signature)
Asst. Dir. - 1-48
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

073

from which this Corner bears *N 21 W*

side of

tree inches diameter, on the

Caplan
Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer. P.O.-7

T. R.