

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

Plotted No 5

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5th Mer.

North $\frac{1}{4}$ Corner common to Sections
31, and 32

Corner consists of an *iron pipe* (not) in place
State condition *good*

Dimensions above ground *2x30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<i>None</i>		

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *None*

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

County Resurvey corner

Dorman J. Sutton

(Signature)

Engineer

(Title)

3-19-35
(Date)

Corner again.

Give any further facts which will aid in finding this


chain distant:

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a *None*



(Make sketch of topography near Corner)

T. 142 N. R. 31 W. 5th Mer. M-5