

U. S. Department of Agriculture
FOREST SERVICE

N-5 ✓

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N. R. 31 W. 5th Mer.

Section Corner common to Sections
17, 18, 19, and 20

Corner consists of a 2" Iron Pipe (not) in place
State condition Good

Dimensions above ground 12 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---|---|------|---|
| | | None | |
| N | W | S | E |

| | | | |
|----|----|------|----|
| | | None | |
| NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|------|--|--|
| | None | | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? NO

If not, why? County Corner

Edward Panek
Edward Panek

(Signature)

Junior Forester

(Title)

3/2/38

(Date)

Corner again.

Give any further facts which will aid in finding this


0.38 chains distant.

from which this Corner bears S. 20° W.

side of Section corner

tree 12 inches diameter, on the North

Metal Location Poster is on a Oak



(Make sketch of topography near Corner)

T. 142 N. R. 31 W. 5th Mer.

N-5