

U. S. Department of Agriculture
FOREST SERVICE

B-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 31 W 5th Mer.

N 1/16 7 56 + 8 55 Corner common to Sections

5, and 6

Corner consists of a 2" I.M. & cap (not in place)


State condition good

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner?

If not, why? On record as set by County

Surveyor. _____

Arthur T. Johnson
Arthur T. Johnson
(Signature)

10/13/38

(Date)

Project Ass't.

(Title)

U.S.

Corner again.

Give any further facts which will aid in finding this

chains distant.

56.


from which this Corner bears

N 80° E

side of

tree 8 inches diameter, on the

Metal Location Poster is on a R. Oak



(Make sketch of topography near Corner)

T. 142 N R. 31 W 5th Mer.

B-5