

U. S. Department of Agriculture
FOREST SERVICE

A-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 31 W 5th Mer.

Section _____ Corner common to Sections
_____, _____, 5, and 6

Corner consists of a 2" I.M. & brass cap (not) in place
State condition good

Dimensions above ground 8 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T142N
R31W
S. 5

Growth
over

--

--

B. T.

--

--

--

Species W. Oak W. Oak

Diameter 8" 10"

Bearing S41°E S54°W

Distance 39 lks. 40 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Arthur T. Johnson
Arthur T. Johnson
(Signature)

Project Ass't
(Title)

10/12/38
(Date)

UK

Corner again.

Give any further facts which will aid in finding this

50 chains distant.

S 20 W


from which this Corner bears

side of

tree 8 inches diameter, on the

Aspen

Metal Location Poster is on a



(Make sketch of topography near Corner)