

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 31 N 5th Mer.

W 1/6 Corner common to Sections

29, and 32

Corner consists of a Cap pipe (not) in place

State condition good

Dimensions above ground 2 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species None

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

County Resurvey

Dorman Sutton

(Signature)

Engineer

(Title)

3-18-35

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


7.80

East

from which this Corner bears

side of post

Metal Location Poster is on a fence post
6 inches diameter, on the West side of post



(Make sketch of topography near Corner)

T. J. HEN. R. 31

M. 6 V-6