

U. S. Department of Agriculture

FOREST SERVICE

R-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N. R. 31 W. 5th Mer.

1/4 Corner common to Sections 20, 29, and

Corner consists of a Iron Pipe (not in place) State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

None			
------	--	--	--

N W S E

None			
------	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	None		

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? NO

If not, why? County Corner

Ed. Panek

Ed. Panek
(Signature)

Junior Forester

(Title)

2/28/38

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant. 0.97

from which this Corner bears N. 20° W.

side of 1/4 Corner

tree 12 inches diameter, on the South

Metal Location Poster is on a Red Pine



(Make sketch of topography near Corner)

T. 142 N. 142 N.

R. 31 W. 5th

Mer.

R-7