

**U. S. Department of Agriculture**  
**FOREST SERVICE**

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 142 N. R. 31 W. 5th Mer.

E. 1/16

Corner common to Sections

17, 20, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a Iron Pipe (~~Box~~) in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

None			

N W S E

None			

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	None		

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing None

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Corner

*E. Panek*  
Ed Panek

(Signature)

Junior Forester

(Title)

3/1/38

(Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this

chains distant.

1.29


from which this Corner bears S. 10° E.

side of

N. 1/16 corner

tree 10 inches diameter, on the North

Metal Location Poster is on a Red Pine



(Make sketch of topography near Corner)

T. 142 N. R. 31 W. 5th Mer.

N-8