

U. S. Department of Agriculture

FOREST SERVICE

P-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N. R. 31 W. 5th. Mer.

1/4

Corner common to Sections

20, 21, and

Corner consists of a Iron Pipe ~~4 1/2~~ in place

State condition Good

Dimensions above ground 15 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

		None	
N	W	S	E

		None	
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	None		

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? County corner

*Ed Panek*

Ed Panek

(Signature)

Junior Forester

(Title)

3/1/38

(Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


0.28 chains distant.

from which this Corner bears N. 56° W.

side of 1/4 CORNER

tree 6 inches diameter, on the South

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 142 N. R. 31 W. 5th Mer.

P-9