

**U. S. Department of Agriculture**  
**FOREST SERVICE**

0-9

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 142 N. R. 31 W. 5th Mer.  
N. 1/16 Corner common to Sections  
20, 21, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a Iron Pipe (~~stone~~) in place  
 State condition Good

Dimensions above ground 12 inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.  
**CARDINAL POSITION** **DIAGONAL POSITION**

	None		
N	W	S	E

	None		
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	None		

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO  
 If not, why? County Corner

*Ed Panek*  
 Ed Panek  
 (Signature)

Junior Forester  
 (Title)

3/1/38  
 (Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


0.45 chains distant.

from which this Corner bears S. 29° E.

side of N. 1/16 Corner

tree 5 inches diameter, on the N. E.

Metal Location Poster is on a Jack Pine



(Make sketch of topography near Corner)

T. 142 N. R. 31 E. 5th Mer.

0-9