

U. S. Department of Agriculture

FOREST SERVICE

Posted 6-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142N* R. *31W* *5th* Mer.

Quarter Corner common to Sections

8, and *9*

Corner consists of a *iron pipe* (not) in place

State condition *fair*

Dimensions above ground *2 1/2* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<i>None</i>		
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>None</i>			

Species *Aspen*

Diameter *4"*

Bearing *S. W*

Distance *60.1k*

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Co. resurvey corner

Donner J. Sutton

(Signature)

Engineer

(Title)

3-14-34
(Date)

573 ch west of U.S. 371
in swamp.

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a *Name*



(Make sketch of topography near Corner)

T. W. R. SIM R. 31W 5th Mer. G-9