

U. S. Department of Agriculture
FOREST SERVICE

B-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 N R. 31 W 5th Mer.

1/16 # 3 S. 4 + # 7 S. 5 Corner common to Sections

4, and 5

Corner consists of a 2" I.M. (533) in place

State condition DOOR

Dimensions above ground 72" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by

County surveyor in 1915.

Arthur T. Johnson
ARTHUR T. JOHNSON
(Signature)

11/3/38
(Date)

Project Ass't
(Title)


USA

Corner again.

Give any further facts which will aid in finding this chains distant.

from which this Corner bears side of

tree inches diameter, on the Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 142 N R. 31 W 5th Mer. B-9