

U. S. Department of Agriculture  
FOREST SERVICE

123  
7-25-37  
[Handwritten initials]

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5th Mer.

NW 1/16 Corner common to Sections

....., and 11


Corner consists of a " I. P. Brass Cap (set) in place  
State condition Good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E NW SW SE NE

1917

Mound of ..... is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species J. P. Snag

Diameter 12

Bearing S70 1/2 E

Distance 60

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Carl Steadland

(Signature)

July 3, 1935

C. F.

(Date)

(Title)

(Make sketch of topography near Corner)


Metal Location Poster is on a

Jack Pine

tree 11 inches diameter, on the

11

side of

from which this Corner bears

N74E

0.16

chains distant.

Give any further facts which will aid in finding this

Corner again.

7294

UNITED STATES GEOLOGICAL SURVEY

WATER RESOURCES DIVISION

Form 1000 (Rev. 1-25-60)

F-18 Mer.

R.

T.