

U. S. Department of Agriculture
FOREST SERVICE

123
7-28-37
OK
6-19-37

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5th Mer.

$C\frac{1}{2}$ Corner common to Sections

11, _____, and _____

Corner consists of a 1" I.P. Brass Cap ~~660~~ in place


State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Aspen R. Oak

Diameter 8 20

Bearing N72W S88E

Distance 7 47

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadland

(Signature)

June 21, 1935

(Date)

C. F.

(Title)

U. S. Department of Agriculture

NATIONAL FOREST

COMMISSIONERS OF THE PUBLIC SURVEY

Section corner to poster

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.07


from which this Corner bears

S72E

side of

tree 8 inches diameter, on the

Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. R.

Mer.

6-19