

U. S. Department of Agriculture
FOREST SERVICE

123
7-27-35
OK
F19
D

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5th Mer.

CN 1/16 Corner common to Sections

, and 11


Corner consists of a 1" I. P. Brass Cap (not) in place

State condition Good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Aspen

Diameter 10

Bearing S30E

Distance 27

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Carl Steadland

(Signature)

July 3, 1935

(Date)

C. F.

(Title)

(Take sketch of topography near Corner)

<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>

Metal Location Poster is on a Aspen

tree 10 inches diameter, on the

side of

from which this Corner bears

N30W

0.27

chains distant.

Give any further facts which will aid in finding this

Corner again.