

U. S. Department of Agriculture
FOREST SERVICE

123
7-28-37
C.S.L.
PP

N-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5th Mer.

Corner common to Sections

13, 14, 23, and 24

Corner consists of a 2" I. P. Brass Cap (set) in place


State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species R. Oak J. P. J. P. J. P.

Diameter 5 9 7 6

Bearing N77 1/2 E N34 1/2 W S66 1/4 W S14 E

Distance 38 60 38 18

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadland

(Signature)

June 13, 1935

(Date)

C. F.

(Title)

Blank lined area for notes.

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.18


N14W

from which this Corner bears

side of

tree 5" inches diameter, on the

Metal Location Poster is on a Jack Pine



(Make sketch of topography near Corner)

T. R. Mer.

N-21