

U. S. Department of Agriculture  
FOREST SERVICE

123  
7-22-37  
066  
J-2  
P

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N. R. 31W. 5th Mer.

Corner common to Sections

11, 12, 13, and 14

Corner consists of a 2" Brass Capped iron Pipe in place

State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

			T142N R31W S11:S12				
N	W	S	S14:S13	NW	SW	SE	NE

Mound of 1915 located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species	N.P.	W.P.	N.P.	W.P.
Diameter	12	12	8	16
Bearing	S77 $\frac{1}{2}$ E	N33 $\frac{1}{2}$ E	N56 $\frac{1}{2}$ W	S46W
Distance	28	21	22	21

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Carl Steadland

(Signature)

June 12, 1935

(Date)

C.F.

(Title)

U. S. Department of Agriculture

FOREST SERVICE

COMMISSIONER OF THE BUREAU OF FOREST SERVICE

Corner again.

Give any further facts which will aid in finding this

chains distant.


0.22

from which this Corner bears S56° E

side of

tree inches diameter, on the

Metal Location Poster is on a 8" N.P.



(Make sketch of topography near Corner)

Mer.

R.

T.

J-21