

U. S. Department of Agriculture  
FOREST SERVICE

*172*  
*7-23-35*  
*201*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5th Mer.

N 1/16 Corner common to Sections  
11, and 12

Corner consists of a "I. P. Brass Cap (not) in place  
State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION

				N 1/16			
				S 11	S 12		
				1917			
N	W	S	E	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species No. B. I.'s found \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Carl Steadland

(Signature)

June 25, 1935  
(Date)

C. F.  
(Title)

*[Faint, illegible text in the top section of the page]*

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.19

from which this Corner bears

N24E

side of

tree 5 inches diameter, on the

Metal Location Poster is on a Red Oak

	Sec.		Sec.
	Sec.		
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R.