

U. S. Department of Agriculture
FOREST SERVICE

123
92837
J222

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5th Mer.

W 1/16 Corner common to Sections
12, and 13

Corner consists of a 1" I. P. Brass Cap (red) in place
State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

			W 1/16	S12 S13			
N	W	S	E	NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

W 1/16 S12BT			

Species W. Pine
Diameter 6"
Bearing N68W
Distance 46

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

Carl Steadland

(Signature)

June 18, 1935 C. F.

(Date)

(Title)

of the location of the corner

CHAIN MARKER

CORNERS OF THE PUBLIC SURVEY

Corner again. Give any further facts which will aid in finding this

0.46 chains distant.

from which this Corner bears S88E

side of

tree 6" inches diameter, on the

Metal Location Poster is on a W. Pine

<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>

(Make sketch of topography near Corner)

T. R. Mer.

J-22