

U. S. Department of Agriculture  
FOREST SERVICE

*E, F-17*

*Chippewa*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142 N* R. *31 W* *5th* Mer.

Witness Corner to ~~Mounded~~ Corner common to Sections  
*10*, and *11* of <sup>*19.77*</sup> <sup>*Chs. South*</sup> <sub>*10/11*</sub>

Corner consists of a *1" I.P. Brass cap* (not) in place  
State condition *Good*

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION \_\_\_\_\_ DIAGONAL POSITION \_\_\_\_\_



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species *Aspen, Spruce, Red Oak*  
Diameter *8*  
Bearing *N 10 E* *S 85 W*  
Distance *10* *18*

Do you believe this to be a genuine Land Office Corner? *Yes*  
If not, why? \_\_\_\_\_

*Carl Steadland*

(Signature)

*July 2, 1935*  
(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

side of

from which this Corner bears *N85E*

0.18 chains distant.

tree <sup>6"</sup> inches diameter, on the

Metal Location Poster is on a *Red Oak*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner) *E, F-17*

T 1420 R 31 W S Mer.