

U. S. Department of Agriculture

FOREST SERVICE

123/57  
7-28-37  
F-192

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5th Mer.

1/64 Corner common to Sections 11 (9.83 E. & 19.80 N, and of C<sub>4</sub> S. 11)

Corner consists of a 1" I. P. Brass Cap (not) in place State condition Good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION DIAGONAL POSITION

				S11				
			AP1					
			TR					
			1588					
N	W	S	E	1917	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species No. B.T.s on 1/64 corners \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Carl Steadland

(Signature)

C. F.

June 24, 1935

(Date)

(Title)

U. S. Department of Agriculture

NATIONAL FORESTS

Corner of the Electric Street

Corner again.

Give any further facts which will aid in finding this

0.15 chains distant.

from which this Corner bears S72W

side of

tree 7 inches diameter, on the

Metal Location Poster is on a Birch

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

F-19'30

Mer.

54

T. 142 R. 31 W.