

Form 874-B—Revised May, 1915  
 U. S. Department of Agriculture  
 FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 31W 5<sup>th</sup> Mer.  
W.C. to Meander Corner common to Sections  
 \_\_\_\_\_, 28, and 27

Corner consists of a Br. cap iron pipe (act) in place  
 State condition good


Dimensions above ground 1.8 1/4 inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch  
 Diameter 7"  
 Bearing N. 17° E.  
 Distance 8

Do you believe this to be a genuine Land Office Corner? Yes  
 If not, why? \_\_\_\_\_

Dorman J. Sutton  
 (Signature)

4/12/35  
 (Date)

Estimator  
 (Title)

UNITED STATES FOREST SERVICE  
DEPARTMENT OF AGRICULTURE  
BUREAU OF FOREST SERVICE  
OFFICE OF THE CHIEF FORESTER  
WASHINGTON, D. C.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *S 12° W*

side of *tree*

tree *8* inches diameter, on the *South*

Metal Location Poster is on a *Birch*



(Make sketch of topography near Corner)

S-T-13 Mer.

5-74

R. B. W.

T. W. B. N.