

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST V-5

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 26 5 Mer.

Sec. cor.

Corner common to Sections

30, 29, 32, and 31

Corner consists of a stake (not) in place

State condition fair

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

T	Sec	R	Sec
143	30	26	32

30	31	32	29

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? county corner

R. T. DeFaut
R. T. DeFaut

(Signature)

2-12-41


(Date)

J. E.

(Title)

Corner again.
Corner is 1.88 chs. N of intersection
of Box River and Remer roads also
adjacent to fence line

Give any further facts which will aid in finding this
corner again.
*01 chains distant.
from which this Corner bears at corner
side of corner
tree 4 inches diameter, on the NE
Metal Location Poster is on a cedar pole



(Make sketch of topography near corner)