

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

T-5

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 26 S Mer.

$\frac{1}{4}$  Corner common to Sections  
29, and 30



Corner consists of a pipe (not) in place  
State condition good

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner **no**

If not, why? **county corner**


*R. T. DeFaut*  
R. T. DeFaut  
(Signature)

J. E.  
(Title)

2-12-41  
(Date)

(Make sketch of topography near Corner)

T. 143 R. 26 Mer. 5



Metal Location Poster is on a cedar fence cor

tree 12 inches diameter, on the East

side of W  $\frac{1}{2}$  cor

from which this Corner bears

° 77

chains distant.

Give any further facts which will aid in finding this

Corner again.

W  $\frac{1}{2}$  cor 13 1.46 chs.

NW of NORWAY Pine