

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

Posted  
11/12/40

Chippewa NATIONAL FOREST V-7

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 26 Mer. 5

$\frac{1}{4}$  Corner common to Sections  
29, and 32

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$ 329			

Species W. P. \_\_\_\_\_

Diameter 30" \_\_\_\_\_

Bearing N45W \_\_\_\_\_

Distance 0.85 \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? no

If not, why? Company Corner

*R. Defant*  
R. Defant (Signature)

10-30-40  
(Date)

J. E.  
(Title)

10-30-40  
 Mer. R. T.

Metal Location Poster is on a tree: 10 inches diameter, on the side of ...  
 from which this Corner bears ...  
 chains distant.  
 shows any further facts which will aid in finding this Corner again.  
 post in center of road

