

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

R-11

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 26 5 Mer.

$\frac{1}{4}$

Corner common to Sections

28, and 21

Corner consists of a Wood Stake (not) in place

State condition Fair

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

N W S E

|  |    |  |    |
|--|----|--|----|
|  | 28 |  | 21 |
|--|----|--|----|

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|               |  |  |  |
|---------------|--|--|--|
| $\frac{1}{4}$ |  |  |  |
| Sec 28        |  |  |  |
|               |  |  |  |

Species Birch

Diameter 18 in.

Bearing SLOW

Distance 10 lks.

Do you believe this to be a genuine Land Office Corner? No

If not, why? county corner

*R. T. DeFant*  
R. T. DeFant  
(Signature)

1-16-41  
(Date)

J. E.  
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant. 00.10

from which this Corner bears N10E

side of N 7/4 COR

tree 18 inches diameter, on the South

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)