

U. S. Department of Agriculture

FOREST SERVICE

CHIPPEWA NATIONAL FOREST

V-15

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 26 5 Mer.

S 1/2

Corner common to Sections

27, and

Corner consists of a stake in place


State condition poor

Dimensions above ground 20 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No.

If not, why? County Corner

Signature of Raymond T. Defant

RAYMOND T. DEFANT

(Signature)

Jr., Civil Engineer

(Title)

3-15-40

(Date)

