

U. S. Department of Agriculture
FOREST SERVICE

G-1
~~675~~
G-1
~~8-25~~
G-1 143-2

~~Shippore~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 20 S. 5 Mer.


1-1 Corner common to Sections
200, 18, and

Corner consists of a not found (not) in place
State condition

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Hick

Diameter 12"

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? not found

Ray De Hart
Ray De Hart

(Signature)

11-30-38

(Date)

77. CIVIL ENG.

(Title)

G-1
~~675~~

Could not find corner - must be
in center-line of road

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of - ~~Boy River Road~~

tree - 3.5 inches diameter, on the west

Metal Location Poster is on a ~~stick~~



(Make sketch of topography near Corner)