

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

A-3

CORNERS OF THE PUBLIC SURVEY

T. *143* R. *27* *5th* Mer.

142 1/2

27

Corner common to Sections

....., *6*....., and *36*.....

Corner consists of a *removed stake* (not) in place

State condition *Log & yellow log (stake)*

Dimensions above ground *52* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why?

Marvin S. Hartman

(Signature)

2/16/59
(Date)

Asst Dist Forester
(Title)

Corner again.

Corner - agreed with [unclear]
Height from the E.N. line [unclear]

Give any further facts which will aid in finding this

2 feet [unclear] distant.

from which this Corner bears *South west* side of

tree *6* inches diameter, on the *South*

Metal Location Poster is on a *corner*

	Sec.		Sec.
	Sec.		Sec. <i>4</i>

(Make sketch of topography near Corner)