

V-7

U. S. Department of Agriculture

FOREST SERVICE

CHIPPEWA

V-7

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5 Mer.

Corner common to Sections

29 32

and

Corner consists of a Brass Cap in place

State condition Good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
29		32	

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter none

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? G. L. C. Brass Cap

RAYMOND T. DEFRANT

(Signature)

Jr. Civil Eng.

12-1-39

(Date)

(Title)

V-7

COMMENTS ON THE FIELD NOTES

Corner again. Approx. 500 ft. south of and across E. R. tracks from see line depot at Boy River


Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of CORNER

tree 8 inches diameter, on the alone

Metal Location Poster is on a Cedar Stake



(Stake sketch of topography near Corner)

Met. V17

5

27

R

143

T