

U. S. Department of Agriculture  
FOREST SERVICE

A-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY A-15

T. 144<sup>143</sup> R. 27<sup>27</sup> Mer. 5

Corner common to Sections

34 T. 144-27, and

Corner consists of a Brass cap (set) in place



State condition good

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Stanley M. Morrison

(Signature)


Forestry and

(Title)

3/24/60

(Date)

A-15



(Make sketch of topography near Corner and show section line markers thus "X")

Metal Location Poster is on a capon tree 8 inches diameter, on the SE side of the from which this Corner bears SE 15 1/2 (Distance) and Section line marker between Secs. 27 and 28 is on a tree, post, etc. on the SE located chains 1, W., N., E., from Sec. (or; 1/4 Cor.; 1/2 W. or Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: Blaze line posted E. & W. of corner