

U. S. Department of Agriculture

FOREST SERVICE

CHIPPewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 27W 5 Mer.

1/4 Corner common to Sections
13, 24, and

Corner consists of a Pine (not) in place

State condition Bad - Burned

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4		1/4	
S13		S24	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

A.H. Jagar

(Signature)

11-13-35

(Date)

Chief of Party

(Title)

Corner again.

Give any further facts which will aid in finding the

0.43


from which this Corner bears

S 30°

side of

two 3 inches diameter, on the S.W.

Metal Location Poster is on a



(Make sketch of topography near corner)