

Form 876-9-20-11-11-11
 U. S. Department of Agriculture
 FOREST SERVICE

2:6,7

CHIPPENAWD NATIONAL FOREST


CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 2. 4 W. 5 Mer.
 Corner common to Sections
 34, 5, and

Corner consists of a Iron Post (not) in place
 State condition Good

Dimension above ground 1 1/2 inches


Sketch (show set, letter, figure, or notch, or proper face or edge)
 CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Buckle) in proper box and
 fill blanks below, giving bearings from Corner to Trees and
 Distances in Feet.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Robert P. ...

(Signature)

Date

Long Lake Shore

corner again.

(Give any further facts which will aid in finding this


corner distant.

from which this corner bears S 87° W

side of Pilling

tree 8 inches diameter, on the W

Actual Location Pole is on a Norway Pines



(Give name of the surveying party)

2-67

143 N R 27 W

SE