

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

101

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY *N-5*

T. *143N* R. *28W* *5P* Mer.

Section Corner common to Sections
19, 20, 18, and 27



Corner consists of a *W Post* (not) in place
State condition *Fair*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *No evidence of B.T.'s - nothing to indicate original survey*

Robert W. ...
(Signature)

3/29/35
(Date)

Estimate
(Title)

Center of Post
3 1/2 in on line
pocket on line

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this corner bears ~~observed~~
side of ~~post~~

tree 4 inches diameter, on the

Metal Location Poster is on a

James Post



(Make sketch of topography near corner)