

Form 574-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

P.

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY L-5

T. 143N R. 28W 5P Mer.

Corner common to Sections  
15, 17, and

Corner consists of a Cedar Stake (not) in place  
State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/4		1/4
	S		SEC
	15		17
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

BT			

Species W. Birch W. Birch  
Diameter 12" 10"  
Bearing N150E S50W  
Distance 0.30 0.10

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence of old  
BT- No old stakes -

Robert Piorela

(Signature)

3/28/35  
(Date)

Estimator  
(Title)

CONTRIBUTORS OF THE BUREAU OF LAND MANAGEMENT

*Direct line*

Corner again

Give any further facts which will aid in finding this

chain distant.


*N 95° E*

from which this Corner bears

side of *tree*

tree 10 inches diameter, on the *NE*

Metal Location Poster is on a *W. Birch (BT)*



(Make sketch of topography near Corner)