

U. S. Department of Agriculture  
FOREST SERVICE

P.

V-15

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N R. 28 W S Mer.

Corner common to Sections  
27, 34, and

Corner consists of a ~~Iron Pin~~ *Good* (not) in place  
State condition *Good*

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|       |      |    |  |
|-------|------|----|--|
| 143 N | 28 W | S  |  |
| S     | 27   | 34 |  |

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|  |  |  |  |

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|        |  |  |  |
|--------|--|--|--|
| 143 N  |  |  |  |
| R 28 W |  |  |  |
| S 34   |  |  |  |

|  |
|--|
|  |
|--|

|  |
|--|
|  |
|--|

|  |
|--|
|  |
|--|

|    |
|----|
| BT |
|----|

|  |
|--|
|  |
|--|

|  |
|--|
|  |
|--|

|  |
|--|
|  |
|--|

Species *Maple*

Diameter *16*

Bearing *S 80° W*

Distance *10.36*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Robert Pearce*

*4/15/31*  
(Date)

*Estimate*  
(Title)

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

SECTION 34

SECTION 37

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree 6 inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 143 N R. 28 W 5th Mer. N-15