

U. S. Department of Agriculture  
FOREST SERVICE

P.

*Chippewa*

T-14, 15

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *143 N* R. *28 W* S. *3* Mer.

*Meander* Corner common to Sections  
*27, 27*, and

Corner consists of a *Gravel mound* (not) in place  
State condition

Dimensions above ground *10* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>N. S. &amp; C. O. S.</i>			
<i>S</i>	<i>ME</i>	<i>27</i>	<i>C</i>

--	--	--	--

N W S E NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Robert R. Ruel*

*7/15/35*  
(Date)

*Estimator*  
(Title)

