

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

V-14, P 15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143N R. 28W 5 Mer.



Meander Corner common to Sections 27, 34, and

Corner consists of a Good Iron Nail (not) in place
State condition Good

Dimensions above ground 16 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Robert Pennington
 4/15/35
 (Date)

Estimate
 (Title)

*along fence line
extending to lake*

Corner again.

Give any further facts which will aid in finding this

~~corner distant.~~

from which this corner bears


at corner

side of

~~tree~~ 6 inches diameter, on the

Metal Location Poster is on a

corner post



(Make sketch of topography near corner)

T. L. MAX R. 222

Mer.

V-145