

U. S. Department of Agriculture

FOREST SERVICE

VW-20 P.

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 28 5 Mer.

MC on 1/4 Sec. Corner common to Sections

NW, NE & NE NE, and Sec. 16.

Corner consists of a 1" Pipe (not) in place


State condition good

Dimensions above ground 1 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

Not tested

W. Skelstrom

(Signature)

E. Skelstrom

(Date)

(Title)


SECTION OF THE PUBLIC LANDS
 THE DISTRICT OF COLUMBIA
 OFFICE OF THE DISTRICT COMMISSIONER

No. 10 of 11
 Section 35

Corner again.

Give any further facts which will aid in finding this chains distant:

From which this Corner bears
 side of about 6 chains
 tree 4 inches diameter, on the East
 Metal Location Poster is on a
 corner post



(Make sketch of topography near Corner)

V. W. 20
 Mer.

T. 14 N. R. 3 E. S. 35