

U. S. Department of Agriculture

FOREST SERVICE

2-89 P.

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

143 & 143 N R. 25 W 5 Mer.

M.C.

Corner common to Sections

32, 5, and

Corner consists of a ~~stone~~ (not) in place

State condition ~~stone~~

Dimensions above ground 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

T 143 N R 25 W			
See 32		Sec 5	M.C.
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

M.C. T 143 N R 25 W Sec 5			
13T			

Species oak

Diameter 14"

Bearing N 79° E

Distance 0.60

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Robert Perrine

(Signature)

3/30/35

(Date)

Estimator

(Title)

REPORT OF INVESTIGATION

NO. 100

WATER RESOURCES DIVISION

UNITED STATES GEOLOGICAL SURVEY

near *Wentworth*  
*Camp - Wentworth*

Corner again

Give any further facts which will aid in finding this

0.66 chains distant.

from which this Corner bears

*\$780W*


side of

tree 14 inches diameter, on the

*W*

Metal Location Poster is on a

*Old BT*



(Make sketch of topography near Corner)

*2-8,9*

Met.

*5*

*J. L. R. R. R.*