

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *143-144* N R. *29W* *5* Mer.

W 1/16 Corner common to Sections

31, *6*, and

Corner consists of a *Iron stake* (not) in place

State condition

Dimensions above ground *7* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>31</i>		<i>6</i>	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>W 1/16</i>
<i>531</i>

<i>W 1/16</i>
<i>56</i>

--

--

<i>BT</i>

<i>BT</i>

--

--

Species *2 Maple^N 1 Birch*

Diameter *13* *8*

Bearing *N 34 E* *550 W*

Distance *25'* *12'*

Do you believe this to be a genuine Land Office Corner? *Y*

If not, why?

O. R. Boerner

Signature.

Estimator

Title.

A-2


12/8/30

Date.

Mof. A-2

5

T. M. W. R. 29th



Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.