

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 29 S. 5 Mer.

1/4 Corner common to Sections

6, 7, and

Corner consists of a Iron Stake (not) in place
State condition Good

Dimensions above ground 4" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Y4</u>
<u>S 7</u>

<u>Y4</u>
<u>S 6</u>

--

--

<u>BT</u>

<u>BT</u>

--

--

Species E1A7

A3H

Diameter 16"

8"

Bearing S 18° W

N 34° E

Distance 10'

13'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

R Willis


Signature.

Estimator

Title.

12/9/30
Date.

(Make sketch of topography near Corner.)



Metal Location Poster is on a _____
 tree _____ inches diameter, on the _____
 side of _____
 from which this Corner bears _____
 _____ chains distant.

Give any further facts which will aid in finding this

Corner again.

Blank lined area for notes, with two punch holes at the top.

T. HAN R. 29 W. 5 / E-3 Mer.