

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 29 5 Mer.

NY16 Corner common to Sections
6, and

Corner consists of a Iron stake in place



State condition good

Dimensions above ground 9" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

NY16
SG

NY16
SG

BT

BT

Species Tamarack Spruce

Diameter 7" 6"

Bearing N 65° E S 86° W

Distance 6' 11'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

R Willis

Signature.

Estimator


Title.

12/8/30

Date.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



8-2027 (Make sketch of topography near Corner.)

T. 143 R. 29 S. Mer. B-3